

03500.017668



Cofe
\$
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
AKIRA HAYAMA) Examiner: Mariceli Santiago
Appln. No.: 10/693,872) Art Unit: 2879
Filed: October 28, 2003)
For: METHOD OF FIXING SPACE)
DEFINING MEMBERS IN AN)
ENVELOPE OF AN ELECTRON BEAM)
APPARATUS)
U.S. Patent No.: 7,063,585 B2)
Issued: June 20, 2006) December 7, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Certificate
DEC 13 2006
of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

38/11/2006 SZENDIE1 03230938 7263595

01 000001


100.00 00

DEC 14 2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

A handwritten signature in black ink, appearing to read 'Frank A. DeLucia', is written over a horizontal line.

Frank A. DeLucia
Attorney for Patentee
Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

604281v1

DEC 14 2003

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,063,585 B2

DATED : June 20, 2006

INVENTOR(S) : AKIRA HAYAMA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"JP 2001252779 A * 9/2001 should read -- JP 2001-252779 A * 9/2001--; and
"JP 2003282003 A * 10/2003" should read --JP 2003-282003 A * 10/2003--.

ON COVER PAGE AT (57) ABSTRACT

Line 8, "to kept" should read --to keep--.

COLUMN 1

Line 26, "that" should read --in which--.

COLUMN 2

Line 14, "causes" should read --the causes--;
Line 61, "where" should read --wherein--; and
Line 63, "a assembling" should read --an assembling--.

COLUMN 3

Line 1, "where" should read --wherein--;
Line 7, "where" should read --wherein--;
Line 8, "influences" should read --influence--; and
Line 11, "where" should read --wherein--.

COLUMN 8

Line 53, "where" should read --wherein--.

COLUMN 9

Line 27, close up right margin; and
Line 28, close up left margin.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,063,585 B2

No. of add'l. copies
@ 30¢ per page



JUN 21 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,063,585 B2

DATED : June 20, 2006

INVENTOR(S) : AKIRA HAYAMA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10

Line 1, "where" should read --wherein--;
Line 3, "where" should read --wherein--; and
Line 55, "where" should read --wherein--.

COLUMN 11

Line 26, "Dxyl" should read --Dyl--; and
Line 46, "has been" should read --have been--.

COLUMN 12

Line 20, "glass, etc." should read --glass, etc.--;
Line 22, "X-directinal" should read --X-directional--; and
Line 45, "Dxyl" should read --Dyl--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,063,585 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

604281v1



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,063,585 B2

DATED : June 20, 2006

INVENTOR(S) : AKIRA HAYAMA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"JP 2001252779 A * 9/2001 should read -- JP 2001-252779 A * 9/2001--; and
"JP 2003282003 A * 10/2003" should read --JP 2003-282003 A * 10/2003--.

ON COVER PAGE AT (57) ABSTRACT

Line 8, "to kept" should read --to keep--.

COLUMN 1

Line 26, "that" should read --in which--.

COLUMN 2

Line 14, "causes" should read --the causes--;
Line 61, "where" should read --wherein--; and
Line 63, "a assembling" should read --an assembling--.

COLUMN 3

Line 1, "where" should read --wherein--;
Line 7, "where" should read --wherein--;
Line 8, "influences" should read --influence--; and
Line 11, "where" should read --wherein--.

COLUMN 8

Line 53, "where" should read --wherein--.

COLUMN 9

Line 27, close up right margin; and
Line 28, close up left margin.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,063,585 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

604281v1



DEC 14 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,063,585 B2

DATED : June 20, 2006

INVENTOR(S) : AKIRA HAYAMA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10

Line 1, "where" should read --wherein--;
Line 3, "where" should read --wherein--; and
Line 55, "where" should read --wherein--.

COLUMN 11

Line 26, "Dxy1" should read --Dy1--; and
Line 46, "has been" should read --have been--.

COLUMN 12

Line 20, "glass, etc." should read --glass, etc.,--;
Line 22, "X-directinal" should read --X-directional--; and
Line 45, "Dxy1" should read --Dy1--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,063,585 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

604281v1



DEC 14 2006